



Dominion

**DAM INSPECTION CHECKLIST
POSSUM POINT POWER STATION
POND ABC**

INSPECTION DATE: 06/20/14

WEATHER: SUNNY; 82°F; LIGHT WIND

INSPECTED BY: JEFF MARVELL

Location/ Condition	(y/n)	Change (y/n)	Comments
Low Point, A dike*			
Flow	Y	Y	SOME WATER COMING FROM WESTERN SIDE OF DIKE
Erosion	N	N	RIP-RAP IN PLACE NO OBSERVED WATER ANYWHERE ELSE *
Low Point, B dike*			
Flow	N	N	SAND BAGS IN PLACE; NO WATER AT LOW EDGE
Erosion	N	N	DRY
Outfall			
water surface El. (top of stoplogs to water)			38"; VERY LITTLE FLOW (LEAK); FLOW CLEAR (HIGH TIDE)

* See figure below.

Additional Comments (Note any changes observed along the embankment crest or downstream slope observed from the crest.):

< 0.10" OF RAIN
FOR WEEK

* - POUNDED WATER AT MIDDLE AND EASTERN EDGE BEHIND BAGS
NO APPARENT BREAKTHROUGH

X1 = POUNDED
WATER
ON ROAD
FROM FERN

X2 = DRY ROAD

